Summary of Major Work Areas (a subset of information in Appendix A1)

		Lease	Est Cost	Sub totals
Description	Clasification	option	£000's	£000's
Re-roof two storey wing				
(note 1)	Inescapable	5 years	150	
	Inescapable total			150
Da mark ain ataman nina				
Re-roof six storey wing,	F	45	00	
upgrade insulation etc	Essential	15 years	90	
General overhaul and				
refurbishment of lift				
motor room equipment,				
lift cars and ropes	Essential	15 years	80	
Twenty year overhaul/				
replacement of boilers	Essential	15 years	70	
	Essential total			240
Refurbishment,				
alteration & upgrade of				
office areas	Highly desirable	25 years	800	
Enhance external				
glazing	Highly desirable	25 years	550	
Defeate Pff Leave Processing		05	00	
Refurb lift landing areas	Highly desirable	25 years	60	
	including some			
	lower value			
	inescapable and			
Other works	essential works		175	
	sub total			1,585
TOTAL				1,975

Note 1: now included in Capital Programme